Approved For Release 2000/04/18 : CIA-RDP81B00879R000500080140-8

RECEIVING INSPECTION REPORT

HYCON MFG. COMPANY

2961 E. COLORADO ST., PASADENA, CALIF.

No. 11402

RECEIVED FROM Eberaliff Electronics Inc.

DATE REC'D 3-5-57

P.O. NO. 69274

VENDOR PACKING SLIP NO. 7293

CHARGE TO	CONTRACT CODE NO.	DRAWING NUMBER	DWG. DASH OR STANDARD PART NO.	DWG. REV.	LOT NO.	CLASS NUMBER	OPER. NUMBER	BUY OUT CODE NO.	O R	ACCT. OR W.O. NO. / S.O. NO.
	322	000000	79	0	23	1				

QUANTITY RECEIVED	DRAWING NO. AND DESCRIPTION	QUANTITY ACCEPTED	QUANTITY REJECTED	REMARKS
100	730151-25 Fuse 2 amp. Slo Blo #MDL-2	100 ✓		

RECEIVED BY [signature] HMC-1000

INSPECTED BY [signature] DATE 3/5/57

REJECTS RETURNED ON SHIP. MEMO NO.

RECEIVING INSPECTION REPORT

HYCON MFG. COMPANY

2961 E. COLORADO ST., PASADENA, CALIF.

No. 11403

RECEIVED FROM PLANT 79

DATE REC'D 2-27-57

P.O. NO.

VENDOR PACKING SLIP NO.

CHARGE TO	CONTRACT CODE NO.	DRAWING NUMBER	DWG. DASH OR STANDARD PART NO.	DWG. REV.	LOT NO.	CLASS NUMBER	OPER. NUMBER	BUY OUT CODE NO.	O R	ACCT. OR W.O. NO. / S.O. NO.
	322	0	17	0	21					

QUANTITY RECEIVED	DRAWING NO. AND DESCRIPTION	QUANTITY ACCEPTED	QUANTITY REJECTED	REMARKS
1	738311 Pin Shuffle Roller	1		
	IPS #A003337			

Approved For Release 2000/04/18 : CIA-RDP81B00879R000500080140-8

RECEIVED BY [signature] HMC-1000

INSPECTED BY [signature] DATE 3/1/57

REJECTS RETURNED ON SHIP. MEMO NO.